

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 7/31/2021 Instrument Serial Number: 100406

Instrument Location: Shaffer Annex Building mile 3 Denali Park Road
Denali National Park, AK 99755

Supervisor Name and Agency: Shelby Barbay, Denali National Park/
National Park Service

Describe the Status Change or Issue with the Instrument:

replacing device that required
maintenance.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: 7/31/2021 1845 hrs

Out of Service Date/Time: ~~7/31~~ SA

For Use by SCDL

Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740