

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 03/09/2020 Instrument Serial Number: 100348

Instrument Location: Officers Room Hall NPPD

Supervisor Name and Agency: Jed Smith NPPD 7569

Describe the Status Change or Issue with the Instrument:

Modem not communicating with the phone line.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 03/09/2020 1714

For Use by SCDL

Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 03/09/2020 Instrument Serial Number: 100348

Instrument Location: Officers Room Hall NPPD

Supervisor Name and Agency: Jed Smith 7569 NPPD

Describe the Status Change or Issue with the Instrument:

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: 03/09/2020 1854

Out of Service Date/Time: _____

For Use by SCDL

Additional Notes

Cermetex box form 100411 installed on 03/11/2020 on the
phone with Derek Watten - SCDL, verified instrument 100348
now communicating with lab. JHW 03/11/20

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740