

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: April 4, 2020 Instrument Serial Number: ~~10424~~ 100424 BMB 4/21/20

Instrument Location: Eielson Air Force Base

Supervisor Name and Agency: Justin Jordan, 354 SFS/Eielson AFB

Describe the Status Change or Issue with the Instrument:

Instrument is being removed from service and returned to Crime Lab for repairs. When attempting to run a test, a status message saying "Filter Wheel Error" is displayed within 5 seconds of starting. The wheels on the inside of the machine make a grinding noise and sound like they are struggling to turn.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: April 4, 2020 / 0930

For Use by SCDL

Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740