

Alaska Scientific Crime Detection Laboratory
Change in Instrument Status Form

Version: 6.0

Effective: 1/17/2024

Date: 7/8/2024

Instrument #: 100422

Instrument Location: Bldg 8517, Joint Base Elmendorf-Richardson

Supervisor Name and Agency: Scott Gardner/JBR4 907-350-6140

Describe the Status Change or Issue with the Instrument:

Operator reported screen unresponsive. Rebooted instrument, no change. Datamaster supervisor verified screen connected internally. Rebooted instrument, screen remains unresponsive. Used keyboard F keys to access system. Instrument indicates incorrect password/access level entered. Instrument removed from service.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: [Click or tap here to enter text.](#)

Out of Service Date/Time: 5 Jul 1100

For Use by SCDL

Additional Notes

[Click or tap here to enter text.](#)

Email completed form to dps.scdl.toxicology@alaska.gov.

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor