

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 10-1-18 Instrument Serial Number: 100402

Instrument Location: Anchorage Jail

Supervisor Name and Agency: D. Henie A.P.D.

Describe the Status Change or Issue with the Instrument:

OUT OF SERVICE
Breath Flow Valve Issue -
Blowing through the tube and no results. The instrument
not getting a breath reading, indicated by the beeping instead of
a solid tone

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 9-30-18 @ 0100 hrs

For Use by SCDL

Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740