

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 9-4-2021 Instrument Serial Number: 100700

Instrument Location: Wrangell P.D.

Supervisor Name and Agency: Bruce Smith, Wrangell P.D.

Describe the Status Change or Issue with the Instrument:

Instrument was working fine. New external control tank was not seating well leaving a small leak. Instrument replaced with 100357.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 9-4-2021 9:00 AM

For Use by SCDL

Additional Notes

Preventive maintenance also due October, 2021 JMT 09/13/21

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740