

Alaska Scientific Crime Detection Laboratory
Change in Instrument Status Form

Version: 6.0

Effective: 1/17/2024

Date: 5/6/24

Instrument #: 100699

Instrument Location: Valdez Jail

Supervisor Name and Agency: Nate Taylor / Valdez PD

Describe the Status Change or Issue with the Instrument:

Had several standard out of range messages on one test
Has been reading the external standard at the low
end of the range.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time:

Out of Service Date/Time: 5/6/24 / 1900

For Use by SCDL

Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov.

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor