

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Effective: 11/10/2021

Version: 2.0

Date: 12/29/21 Instrument #: 100695

Instrument Location: Talkeetna - South Denali Ranger Station

Supervisor Name and Agency: Lee Phillips AST

Describe the Status Change or Issue with the Instrument: Failed VOC, Replaced with # 100381.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time:

Out of Service Date/Time: 12/29/21 @ 2030 hours

Table with 2 columns: For Use by SCDL, Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740