

Alaska Scientific Crime Detection Laboratory
Change in Instrument Status Form

Version: 6.0

Effective: 1/17/2024

Date: 3/26/2025

Instrument #: B-100668

Instrument Location: North Pole Police Department

Supervisor Name and Agency: Travis W. Koerner, NPPD

Describe the Status Change or Issue with the Instrument:

The Instrument is having a continuous "Filter Wheel Error" Status Message. After several attempts at running the filter test and rebooting, it is still displaying the same Status Message.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: Click or tap here to enter text.

Out of Service Date/Time: 03/23/2025 0355 hours

For Use by SCDL

Additional Notes

Click or tap here to enter text.

Email completed form to dps.scdl.toxicology@alaska.gov.

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor