

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 6/11/2014
Effective: 6/11/2014

Version: CIISF 2014 R0
Status: Active

Date: 12/6/2017 Instrument Serial Number: 100396

Instrument Location: Anchorage Jail (South DMT in South room)

Supervisor Name and Agency: Freitag 7364 APD

Describe the Status Change or Issue with the Instrument:

DMT began throwing several errors, to include BLANK, EXTERNAL. Test sample run and overly vigorous pressure was needed to get above 3.06/min.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 12/6/2017 / 15:30

| For Use by SCDL | Additional Notes |
|-----------------|------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Email completed form to rus.scdl@alaska.gov
For questions contact the Breath Alcohol Program at 907-269-5740