

Alaska Scientific Crime Detection Laboratory  
Change in Instrument Status Form

Version: 4.0

Effective: 8/10/2022

Date: 9/22/2022

Instrument #: 100687

Instrument Location: Galena PD

Supervisor Name and Agency: Carlie Glaister (SCDL) and Kelcey Harrison (Galena PD Point of Contact)

Describe the Status Change or Issue with the Instrument:

During IFIR 2022.05.31 – 2022.07.18 it was recommended to monitor instrument 100687 due to tank interference and internal standard errors. During the most recent IFIR (2022.07.19 – 2022.09.05) there were no tests aside from 1 VOC with no status messages. I emailed the point of contact for Galena PD, Kelcey Harrison requesting at least 1 breath test be run over 5 days to gather more data to determine the monitoring status of the instrument for next IFIR.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: [Click or tap here to enter text.](#)

Out of Service Date/Time: [Click or tap here to enter text.](#)

-----  
**For Use by SCDL**

**Additional Notes**

[Click or tap here to enter text.](#)

**Email completed form to [dps.scdl.toxicology@alaska.gov](mailto:dps.scdl.toxicology@alaska.gov)**  
For questions contact the Breath Alcohol Program at 907-269-5740

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor