

# Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Issued: 12/15/2017  
Effective: 12/15/2017

Version: CIISF 2017 R0  
Status: Active

Date: 4 Jun 19 Instrument Serial Number: 100421  
Instrument Location: JBR 4  
Supervisor Name and Agency: Scott Gordon

Describe the Status Change or Issue with the Instrument:

return from repair @ Lab

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: 1130 - 4 Jun 19  
Out of Service Date/Time: \_\_\_\_\_

For Use by SCDL

Additional Notes

Email completed form to [dps.scdl.toxicology@alaska.gov](mailto:dps.scdl.toxicology@alaska.gov)

For questions contact the Breath Alcohol Program at 907-269-5740