

Alaska Scientific Crime Detection Laboratory
Change in Instrument Status Form

Version: 6.0

Effective: 1/17/2024

Date: 15 MAY 2025

Instrument #: 100361

Instrument Location: JBR4 Joint Base Elmendorf Richardson

Supervisor Name and Agency: Scott Gardner/JBR4

Describe the Status Change or Issue with the Instrument:

Instrument was on loan from lab.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: Click or tap here to enter text.

Out of Service Date/Time: 15 May 25/0900

For Use by SCDL

Additional Notes

Click or tap here to enter text.

Breath hose has an electrical short + should
be replaced. Per Scott Gardner to C. Bryant.
Temperature of breath hose could fluctuate
with physical movement of the hose.

CDL 5/15/25

Email completed form to dps.scdl.toxicology@alaska.gov.

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor