

# Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Issued: 12/15/2017  
Effective: 12/15/2017

Version: CIISF 2017 R0  
Status: Active

Date: 2/26/2020 Instrument Serial Number: 100360

Instrument Location: Sand Point

Supervisor Name and Agency: Mark Chandler/SPPD

Describe the Status Change or Issue with the Instrument:

Gas flow error. Replaced tank. Inspected white double check valve.

No gas flow error after tank change.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: 2/26/2020/1130

Out of Service Date/Time: \_\_\_\_\_

-----  
**For Use by SCDL**

**Additional Notes**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Email completed form to [dps.scdl.toxicology@alaska.gov](mailto:dps.scdl.toxicology@alaska.gov)

For questions contact the Breath Alcohol Program at 907-269-5740