

Alaska Scientific Crime Detection Laboratory
Change in Instrument Status Form

Version: 4.0

Effective: 8/10/2022

Date: 7/22/2023

Instrument #: 100667

Instrument Location: Anchorage Jail

Supervisor Name and Agency: Derek Sitz Anchorage Police Department

Describe the Status Change or Issue with the Instrument:

Tank change to correct lot number, specifically remove the B which was put incorrectly on last tank change

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: ~~07/22/2023 0400~~ Instrument already in service CKG 08/08/2023

Out of Service Date/Time: Click or tap here to enter text.

For Use by SCDL

Additional Notes

Click or tap here to enter text.

The lot # was entered incorrect as "BAG135004" during the tank change that occurred on 06/11/2023. The incorrect lot # was present on 2 VOCs (06/11/2023 and 07/18/2023). Another tank change occurred on 07/22/2023 and the lot # was corrected. All breath tests that occurred between 06/11/2023 and 07/21/2023 have the incorrect tank lot # on them. CKG 08/01/2023

Email completed form to dps.scdl.toxicology@alaska.gov
For questions contact the Breath Alcohol Program at 907-269-5740

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor