

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 12 Feb 2020 Instrument Serial Number: 100422

Instrument Location: JPR 4 -

Supervisor Name and Agency: Scott Gordon - JPR 4

Describe the Status Change or Issue with the Instrument:

Detected OVERTOW -

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 1705 - 12 Feb.

For Use by SCDL	Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740