

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 5/13/18 Instrument Serial Number: 100406

Instrument Location: Palmer PD

Supervisor Name and Agency: Sgt. Szipszky, Palmer PD

Describe the Status Change or Issue with the Instrument:

The white piece at the end of the breath tube hose was ripped out and broke the glue seal.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 5/13/18 0745

For Use by SCDL	Additional Notes
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740