

# Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Issued: 6/11/2014  
Effective: 6/11/2014

Version: CIISF 2014 R0  
Status: Active

Date: 6/28/16 Instrument Serial Number: 100417

Instrument Location: TUNEAU PD

Supervisor Name and Agency: Steeley Salsbery

Describe the Status Change or Issue with the Instrument:

Per Breake

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: \_\_\_\_\_

Out of Service Date/Time: 6/28/16, 0736 hours

For Use by SCDL

Additional Notes

Suck back error on Infield inst review. BMB 8/10/16

Email completed form to [dps.scdl.toxicology@alaska.gov](mailto:dps.scdl.toxicology@alaska.gov)

For questions contact the Breath Alcohol Program at 907-269-5740