

# Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Issued: 6/11/2014  
Effective: 6/11/2014

Version: CIISF 2014 R0  
Status: Active

Date: 6/10/16 Instrument Serial Number: 100420

Instrument Location: Ft. Greely

Supervisor Name and Agency: Brandi Barnett SCDL

Describe the Status Change or Issue with the Instrument:

Instrument out of service due to expired tank.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: 6/10/16 14:33

Out of Service Date/Time: 5/1/16

For Use by SCDL

Additional Notes

Email completed form to [dps.scdl.toxicology@alaska.gov](mailto:dps.scdl.toxicology@alaska.gov)

For questions contact the Breath Alcohol Program at 907-269-5740