Version: 6.0			ne Detection La Iment Status		Effective: 1/	17/202	24
Date: 2650624	lr	nstrume	nt #: ØØ69_	5			
Instrument Location: RM	197, BLDG-66	Ø, FT.	GREELY	AK 9	9731		
Supervisor Name and Agency: LIPS COMB, FGPD							
Describe the Status Change	or Issue with the	Instrum	ient:	21 - :			
LOANER INSTRU	NENT, OUT	OF	SERVICE	FOR	RETURN	70	LAB

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time:

Out of Service Date/Time: 0909, 2650424

For Use by SCDL

Additional Notes

Loaner instrument is still calibrated upon arrival. MNC 8/6/24

Email completed form to dps.scdl.toxicology@alaska.gov.

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor

100695 2024.07.26 Change In Status