Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Date:	20 OCT 2021	Instrument Serial Number: 100645
Instrur	ment Location:	AUT Emmonak POST
Superv	visor Name and Agend	ey: Tatiana Let - Ascol
Descri	be the Status Change	or Issue with the Instrument:
	DMT taken out	of service due to an expired fank.
In Ser	rument was placed in vice Date/Time:	service or removed from service, fill out the appropriate sections below. 22 Aug 2021
For U	se by SCDL	Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740