

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 4/8/21 Instrument Serial Number: 100375

Instrument Location: Shaffer Annex, mile 2 Denali Park Road

Supervisor Name and Agency: Shelby Barbay, Denali National Park

Describe the Status Change or Issue with the Instrument:

Old unit out of service.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: _____

Out of Service Date/Time: 1500 hrs 4/8/21

For Use by SCDL

Additional Notes

Removed from service because preventive maintenance was due DJW 04/21/2021

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740